


# CA1

## Cathodic Protection

Horizontal thru cable  
to horizontal pipe




### Khuôn hàn hoá nhiệt CA1

Conductor	Metal Powder (g)	Graphite Mould Type	Handle Clamp Type
A mm <sup>2</sup>			
2.5	15	CA1-A-2.5	HCA
4	15	CA1-A-4	HCA
6	15	CA1-A-6	HCA
10	15	CA1-A-10	HCA
16	15	CA1-A-16	HCA
25	15	CA1-A-25	HCA
35	32	CA1-A-35	HCA
50	65	CA1-A-50	HCA
70	65	CA1-A-70	HCA

# CA2

## Cathodic Pro

Horizontal thru cable  
to horizontal pipe



### Khuôn hàn hoá nhiệt CA2

Conductor	Metal Powder (g)	Graphite Mould Type	Handle Clamp Type
A mm <sup>2</sup>			
2.5	25	CA2-A-2.5	HCA
4	25	CA2-A-4	HCA
6	25	CA2-A-6	HCA
10	25	CA2-A-10	HCA
16	25	CA2-A-16	HCA
25	25	CA2-A-25	HCA
35	45	CA2-A-35	HCA
50	65	CA2-A-50	HCA
70	65	CA2-A-70	HCA

### Tools Request :



Mould



Mould brush



Handle clamp



Metal powder



Steel disk



Flint igniter



Bus bar brush